

25X1

0945Z 22 JAN 63

SECRET

DIRECTOR

25X1

OSA (1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16)

S/C (17)

25X1

TOR: 1035Z 22 JAN 63

IN 63322

25X1

PRITY

INFO PRITY

CITE

0646

25X1

NO NITE ACTION

25X1

REF A 879

25X1

B 41

C 0371

25X1

1. FROM [ ] NO VACUUM FAILURE EVIDENT ON POST OP

25X1

25X1

INSPECTION MSN G-3213. VACUUM IS VISUALLY GROUND CHECKED WITH  
 MSN [ ] PRIOR TO INSTALLATION IN [ ] AND IMMEDIATELY  
 AFTER REMOVAL PRIOR TO UNLOADING [ ]

2. VACUUM VALVE SM-33 WAS USED ON THIS MSN (ALSO ON MSN  
 G-3213). THIS UNIT WAS DRAWN FROM FAK AND INSTALLED JUST PRIOR  
 TO G-3213, AFTER ADJUSTMENT AND TREATMENT PER REF B. ONLY CYCLES  
 WERE 3560 FROM G-3213. TEAR DOWN AFTER MSN REVEALED LITTLE OR  
 NO WEAR AS REPORTED IN REF C.

25X1

3. [ ] (REF A) WAS NOT RECEIVED UNTIL AFTER LAUNCH  
 MSN G-3215.

25 YEAR RE-REVIEW

END OF MESSAGE

SECRET

GROUP 1  
 Excluded from automatic  
 downgrading and  
 declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.